





Robert J. Hennick, et al.
Our Docket No.: 283-309.11

For: OPTICAL READER IMAGING MODULE
Attorney of Record: George S. Blasiak
Telephone: (315) 425-9000
40 Pages of Drawings

















Fig 5c
























10,10-22 Le a'i 640 640 25 . Fly EN 259 18 Fig 6p



























































110,110d

